



PN G1 G2 C1 C2 L A H Sw Cu

16 1/2" 1/2" 20 11,5 80 26 26 19 15

T = 0 °C...+90 °C